## 

THE RESERVE OF THE PARTY OF THE	Date				
ROUTING AND TRA	NSMITTA	Date	11	100	
			6/15/	87	
TO: (Name, office symbol, room	n number,		Ínitials	Date	
building, Agency/Post)	11				
1.	Masselberge	1		X .	
A	- 200				
2.	1-085			4.5	
3.			STATE OF	10000000	
	AV.		The section		
4. The second of					
21					
5.	J. ()	la.			
Action	File For Classes		Note and Return		
Approval	For Clearance	_	Per Conversation		
As Requested Circulate	For Correction For Your Information		Prepare Reply See Me		
Comment	Investigate		Signature		
Coordination	Justify	Olgii	Olgitature		
DEMARKS					
The state of the s					
O Vino Chang in a D					
D believe there is a to					
action outstanding on this					
-0		1			
1to.					
1200	~ 1				
	(0/)				
	WARSIT	القال	MISS	(Iri)	
REGENVEIN					
	JUI	V 19	1989	and the second	
	DEC.				
DO NOT use this form as cle	a RECORD of approvals	Concu	trendes	disposals,	
	FPA		N 10	No.	
FROM: (Name, org. symbol, A	gency/Post)	Ro	om No.—	-Bldg.	
1/19	1 /	-	To the Co	182.73	
NV A	tra seen / 19 de	Ph	one No.		
5041-102	OPTIO	NAL EC	RM 41 (Re	av 7.76)	
3041-102	OPTIO	MAL PU	KW 41 (K	. 1-10)	

GPO: 1987 0 - 196-409

FPMR (41 CFR) 101-11.206

6/25 89 41,03,06 A Aretrainet greated & attrophotation within



## Department of Environmental Quality

811 SW SIXTH AVENUE, PORTLAND, OREGON 97204-1390 PHONE (503) 229-5696

June 8, 1989

Mr. Stanford Nudelman 2707 N.W. Nela St. Portland, OR 97210

> Re: Nudelman & Son, Inc Preliminary Assessment ORD # 027744093

The Department of Environmental Quality (DEQ) has completed a preliminary assessment of Nudelman & Son Inc. under an agreement with the U.S. Environmental Protection Agency (EPA). A copy of the report with the attachments is enclosed. A preliminary assessment is an initial assessment of available information about a site to establish whether there are sufficient human health and\or environmental concerns to warrant a more extensive review.

Based on the preliminary assessment, DEQ recommends that no further action be performed under the EPA Superfund program. However, it is recommended that the EPA TSCA program follow-up on the removal of the transformer containing PCBs. There is also some concern with regard to the low level of contamination and the capacitors outside the fence near the access road. DEQ does not anticipate further action at this site unless additional information becomes available which warrants investigation. Please feel free to submit information to us which you believe would make our report more complete.

If you have any questions, please call Michael Zollitsch of my staff at (503) 229-6931.

Sincerely,

David St Louis, P.E., Manager

Site Assessment Section

Environmental Cleanup Division

MZ:m SM2321 Enclosure

cc: Debbie Flood, Region X, EPA
AL Goodman, EPA 000
Ed Woods, NWR, DEQ
Michael Zollitsch, DEQ

RECEIVED

JUN 15 1989

OREGON OPERATIONS OFFICE EPA-REGION 10